

DAFTAR PUSTAKA

Anonim(2018) <http://e-journal.uaiy.ac.id/443/3/2EP17034.pdf>, diakses tanggal 24 April 2020

Anonim(2017) <https://www.bahankain.com/2019/08/21/mengenal-jenis-cacat-pada-kain>, diakses tanggal 24 April 2020

Anonim, (2020).*Buku Pedoman Praktik Kerja Lapangan Akademi Komunitas Industri Tekstil dan Produk Tekstil Surakarta*. Kementerian Perindustrian, Surakarta.

Anonim, (2018). *Company*, <https://www.duniatex.com/id/company.html>

Departemen Weaving 5 PT Delta Merlin Dunia Textile V, 2020

Personalia PT Delta Merlin Dunia Textile V,2020

Inspecting PT Delta Merlin Dunia Textile V, 2020

Widati (2002: 135) dan Poerwadarminta, (1989: 32)

LAMPIRAN

lampiran 1 Kartu Inspect mc no. 941

FABRIC INSPECTION RECORD PT DMDT V																	
KONSTRUKSI						KONSTRUKSI											
TGL POT / INSP						TGL POT / INSP											
NAMA OPR / SHIFT						NAMA OPR / SHIFT											
NO. MC LOOM						NO. MC LOOM											
NO. BEAM / SERI						NO. BEAM / SERI											
LEBAR KAIN (ACT)						LEBAR KAIN (ACT)											
TETAL LUSI (ACT)						TETAL LUSI (ACT)											
TETAL PAKAN (ACT)						TETAL PAKAN (ACT)											
PANJANG KAIN						PANJANG KAIN											
DEFECT ALL GRADE			TENUN AWAL			INSPECT (PERBAIKAN)			DEFECT ALL GRADE			TENUN AWAL			INSPECT (PERBAIKAN)		
			3 5 10			3 5 10						3 5 10			3 5 10		
PKB																	
MISS PICK																	
DPS																	
NETTING																	
SMG																	
DOUBLE LUSI																	
LOOP																	
FLOAT																	
SALUR																	
PUTUS LUSI KOSONG																	
LTP																	
LTB																	
SISA LUSI																	
TENUN						INSPECT (PERBAIKAN)											
MTR	SHIFT	DP	LTB	LTP	SMG	MTR	DP	LTB	LTP	SMG	MTR	SHIFT	DP	LTB	LTP	SMG	
5						5					5						
10						10					10						
15						15					15						
20						20					20						
25						25					25						
30						30					30						
35						35					35						
40						40					40						
45						45					45						
50						50					50						
55						55					55						
60						60					60						
65						65					65						
70						70					70						
75						75					75						
80						80					80						
85						85					85						
90						90					90						
95						95					95						
100						100					100						
105						105					105						
110						110					110						
115						115					115						
120						120					120						
125						125					125						
130						130					130						
135						135					135						
140						140					140						
145						145					145						
150						150					150						
155						155					155						
160						160					160						
165						165					165						
170						170					170						
175						175					175						
180						180					180						
185						185					185						
190						190					190						
195						195					195						
200						200					200						
205						205					205						
210						210					210						
215						215					215						
220						220					220						
225						225					225						
230						230					230						
235						235					235						
240						240					240						
245						245					245						
250						250					250						
255						255					255						
260						260					260						
265						265					265						
270						270					270						
275						275					275						
280						280					280						
285						285					285						
290						290					290						
295						295					295						
300						300					300						

lampiran 3 Kartu Inspect mc no. 593

RECORD PT DMOY

NO. INSTRUMEN: R 245653 55 80

TGL. POT / INSP: 21/11/2017

NAMA OPR / SHFT: 6-15-33 PL

NO. MC / LIDOM: 593

NO. DRAM / BWT: 130710

LEBAR KAN (ACT): 017-35

PETAL LUB (ACT): 84

TR. TAL. PAKAN (ACT): 56

PANJANG KAN: 70

370

DEFECT ALL GRADE: TEMUN AWAL: INSPEKSI (PERBAIKAN)

3 5 10 0 5 10

PKB

MSB POKA

DPS

NETTING

SMG

DOUBLE LUB

LOOP

F. DAT

EAL. MS

PUTUS LUB KOSONG

LTP

LTR

MSA LUB

pb dps jarang

TEMUN					INSPEKSI (PERBAIKAN)					
MTR	SHFT	DP	LTD	LTP	SMG	MTR	DP	LTD	LTP	SMG
5						5				
10						10				
15						15				
20						20				
25						25				
30						30				
35						35				
40						40				
45						45				
50						50				
55						55				
60						60				
65						65				
70						70				
75						75				
80						80				
85						85				
90						90				
95						95				
100						100				
105						105				
110						110				
115						115				
120						120				
125						125				
130						130				
135						135				
140						140				
145						145				
150						150				
155						155				
160						160				
165						165				
170						170				
175						175				
180						180				
185						185				
190						190				
195						195				
200						200				
205						205				
210						210				
215						215				
220						220				
225						225				
230						230				
235						235				
240						240				
245						245				
250						250				
255						255				
260						260				
265						265				
270						270				
275						275				
280						280				
285						285				
290						290				
295						295				
300						300				

100 = 0,42

233

100

233 = 0,42

langka

langka

90-015

90-015

lampiran 6 Penyebab Cacat Tebal Tipis

1. Breaklinning Pecah



(Breaklinning yang utuh)




(Breaklinning yang pecah)

2. Rubberstrip Tumpul /halus



(Rubber Strip yang tajam)



(Rubber Strip yang sudah tumpul)

3. Bantalan beam (metal bush) patah atau terlalu banyak gesekan



(Bantalan beam yang normal)



(Bantalan Beam yang terkena gesekan)